AT1103M X-ray radiation dosimeter
No.412159.016

Standard delivery set

Accessories set
No.412914.053

Cap *No.305131.006* [Mounted on instrument]	
Handle *No.301156.004-02* [Mounted on instrument when "Bag for standard set" is selected as a delivery option]	
Strap *No.301547.001* (Hand)	
Power adapter *SA110C-12GS-I* (Cable length is 1.5 m; adapter can be replaced by a unit with identical characteristics)	
Holster *H-1121-03M*	

User's manual (Hard copy)

AT1103M X-ray radiation dosimeter		Options
Kit for connecting the dosimeter to PC USB-port *No. 412918.068*	**DU cable** *No. 685621.067* (Instrument →USB-DU adapter, length 1.2 m) [1)] **USB-DU Adapter***No.436121.013* **USB A-B cable** (USB-DU adapter→PC, length 1.8 m) **"ATexch" Software** (on external media) **"ATexch" Software User's Manual** (Hard copy)	 
Kit for connecting the dosimeter to PC COM-port *No. 412914.047*	**Interface cable** *No.685621.035* (Instrument →PC, length 1.9 m) [1)] **"ATexch" Software** (on external media) **"ATexch" Software User's Manual** (Hard copy)	
[1)] Length of **cable** can be increased up to 25 m, if necessary		
Cable *No.685621.003* (For charging the instrument from 12 V source, length 1.4 m)		
Kit for working with telescopic bar, 1.7 m *No.412918.063*	**Telescopic bar 1.7 m***No.301524.016* (With shoulder strap, supplied in bag) **Holder** *No.301568.002* (For attaching the instrument to telescopic bar)	
Carry bag *No.305636.021* [For standard delivery set]		
Case *№305648.030* [For standard delivery set / Remote Control / Accessories (except of telescopic bar)]